



Figure 3 (to Supplement #2 to FER-240). Faults recommended for incorporation into the Earthquake Fault Zones Map of the Cucamonga Peak 7.5-minute quadrangle (modification of sections 16 and 17). Fault traces highlighted in yellow are from Rasmussen and Associates (1989, 1990). Dotted traces in brown are traces of Strand A mapped by Morton and Matti (1987) recommended to be removed.